

---

Subject: Re: A-4 Repair

Posted by [steven](#) on Fri, 09 Feb 2018 13:32:58 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

If you have installed the right 3900 ohm resistors then it's time to start doing some voltage test, like on Q701,702 and 703, as I think this is where your issue is, in fact it would be tempted to just shotgun in all 3 Transistors as your talking about 5 bucks in parts!

---