
Subject: Re: Kustom 100 blowing fuse
Posted by [steven](#) on Tue, 23 Apr 2019 16:13:34 GMT
[View Forum Message](#) <> [Reply to Message](#)

Even 20% tolerance resistors in those two locations would not make the amp blow or not work. The 5 watt resistors should be matched as close as possible .
I order 10 to 15 of them at a clip and test them resistance wise to match them with my ESR cap checker as it's far more accurate then the average multimeter.
