

---

Subject: Re: Schematic Accuracy

Posted by [bluezebra](#) on Mon, 10 Feb 2014 22:33:47 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Grounding the intensity pot did not help. I did notice that the +8 is at +10.6 and the -8 side is at -9.4. I'm assuming that it is higher due to higher line voltages since the sixties?

---