

---

Subject: Re: Repair

Posted by [steven](#) on Sat, 09 Apr 2022 14:11:46 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

If I had to guess at the volume drop off issue your having it would be the two electrolytic caps at each end of the intensity control .

One is a 10 uf and if I recall right the other is a 33 Uf.

This circuit board is a good bit of a pain in the Ass to get out, so if you go thru the work to do that then replace all off the electrolytic type caps and get it done in one shot.

Is your reverb working right now?

---