

---

Subject: Re: A-4 Repair

Posted by [steven](#) on Thu, 01 Feb 2018 13:23:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

So your saying at C702 where there should be a 10uf electrolytic cap there is now a 22 uf cap with another disc cap in parallel with it? If so remove the second cap and if that 22 uf cap is good then that can stay there for now until we get the board working.

This other .02 uf ceramic cap on the rear of the board that you say has one end going to ground , where does the other end land at?

I do not have a board of my own out to look at the trace side so you need to tell me where that what looks like a added cap goes to schematic wise!

---