Subject: Re: Schematic Accuracy Posted by chicagobill on Mon, 10 Feb 2014 17:40:38 GMT View Forum Message <> Reply to Message

Like all manufacturers, all of the production changes at Kustom may or may not have been fully documented. And even if they were, they may not have made it to the general dealership network where most of the available on-line schematics have come from.

I usually don't worry about mismatches unless there is a known common problem that can be fixed by a circuit revision.

Regarding the tremolo thumping, when you turn down the intensity control does it go away? And of course, if you turn it off with the footswitch it stops, correct?

