

---

Subject: Re: A-4 Repair

Posted by [Jonomega3](#) on Thu, 01 Feb 2018 16:13:11 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Yes, the 22uf electrolytic is coupled with a small disk 1kv cap. I have a good new 10uf 16v that I can put in that spot which I believe is correct value for C702? The other end of the ground ends up at R713, 714 and 715 in that area. Im pretty certain that large .02 disk cap is not supposed to be in there, it is very sloppily affixed to the board and I went through the schematics a couple times to account for all other caps.

---