

---

Subject: Re: Repair

Posted by [steven](#) on Sat, 09 Apr 2022 21:14:21 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

That ground wire was only in the early amps.

---