

---

Subject: Re: A-4 Repair

Posted by [steven](#) on Sun, 19 Aug 2018 10:15:30 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Well it's time to yank the driver transistors Q708 and Q704 and test them and also check that the 1 ohm 5 watt resistors have not be blown open.

---