Subject: Re: A-4 Repair

Posted by Jonomega3 on Sat, 25 Aug 2018 15:43:04 GMT View Forum Message <> Reply to Message

Shouldn't respond till I've had at least a second cup of coffee, LOL! You are saying there should be -0.5 volts at the base, sorry for the misunderstanding