

---

Subject: Re: Kustom 100 blowing fuse

Posted by [timetraveler](#) on Tue, 23 Apr 2019 14:42:24 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

according to the schematic the r23 and r25 are supposed to be 150 ohm 1% the ones in my board now are 150 ohm 10% and not measuring to 1% so replacing those along with r26 ... waiting on the parts. meanwhile gonna recheck transistors to see if they got screwed up because i turned on with resistors out of tolerance.

---