Subject: Re: Kustom 100 blowing fuse
Posted by timetraveler on Sun, 14 Apr 2019 23:05:25 GMT
View Forum Message <> Reply to Message

Retested output transistors and one was blown. I replaced with a new transistor and turned on =blew a fuse again. Rechecked newly installed transistor and it is blown.   I'm thinking I somehow managed to switch the yellow and blue leads around or is there something else that would cause the transistor to blow.