Subject: Re: Kustom 100 blowing fuse
Posted by timetraveler on Sat, 13 Apr 2019 16:08:13 GMT
View Forum Message <> Reply to Message

john

The the red and green wires WERE connected to all of the boards and the fuse did not blow when the molex was unplugged

I had disconnected both green and red from filters previously  (not just the red as stated in previous post),

Ill be checking the caps next