

---

Subject: Re: 250-4

Posted by [kb0rex](#) on Thu, 14 Jul 2022 16:09:57 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

for now the amp is not pulling down the power supply and is running cool to the touch. Looks like maybe the amp portion is ok and time to move upstream.

---