

---

Subject: Re: Repair

Posted by [NLKustom](#) on Thu, 07 Apr 2022 22:35:55 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Update:

So it turns out the reverb tank was put in backwards with the output by the power transformer. Switched it around all the reverb hum disappeared. With no loss of volume. Thanks for the valuable info Steve.

But I am getting a bit of loss in volume and a bit less clearer tone when I turn on the intensity effect.

---