
Subject: Re: K150-6 pumps out DC voltage when powered on.
Posted by [corybrown](#) on Sun, 15 Mar 2020 14:51:42 GMT
[View Forum Message](#) <> [Reply to Message](#)

I have tried so many things I'm losing track.

Q4 has been replaced with a brand new nte128.

I tested with Q7 out of the circuit and experience the same behavior.

I tested with CR4 and CR5 out of the circuit and with replacement parts 1n4d004 and also tried NTE177. Same behavior.

Last night I took out Q5 and Q6 and put in NTE128 and NTE129 and again same behavior.
