

---

Subject: Re: A-4 Repair

Posted by [Jonomega3](#) on Mon, 12 Feb 2018 14:04:49 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

"I would also lift one end of cr704 and cr705 to test them for shorts or leakage."

Cant seem to find these components you mentioned on my PC 702 board as well as Q705 and Q709 but they are showing up on the schematics.

---