

---

Subject: Re: K150-6 pumps out DC voltage when powered on.

Posted by [corybrown](#) on Sun, 30 Aug 2015 17:42:51 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I checked all of the components on pc5032 and all seem to be solid. There definitely seems to be something loose as it has worked a few more times and each seems to be right after moving the amp chassis around. Today I fired it up and it worked for about 2 minutes and then went back to making the humming noise.

I'm pretty good with soldering, but usually it's replacing a visible bad cap. Other than seeing a leaky cap I'm not very good at locating bad components. I'm probably going to have to take it someone here local, just not sure who works on things like this in my area. You guys know of any good techs in the Huntington or Charleston WV area?

---