
Subject: 1974 Kustom 1-b bass amp

Posted by [Hugh Andrews](#) on Thu, 20 Sep 2018 23:54:12 GMT

[View Forum Message](#) <> [Reply to Message](#)

Dug this amp out after many years of none use and it had 2 problems. 1) popping and crackling 2) and each note fades distorted (buzzing) at any volume. I replaced the electrolytic caps with 4700uf 50v caps instead of the 1900uf 40v caps as per suggestions from this forum and that solved problem #1. Notes are loud and strong, but as they decay it's distorted. I tried different guitars and cables. I disconnected the amp from the speaker and drove the speaker with another amp. It did not distort. So the problem is not in the speaker or cabinet. Does this sound like a problem in the power section or the preamp? Or possibly the transformer? Also I cannot find a schematic. Any suggestions?

Subject: Re: 1974 Kustom 1-b bass amp

Posted by [steven](#) on Fri, 21 Sep 2018 09:56:37 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hello and welcome!

Sorry that your post could not be loaded right onto the site, but we have been getting very heavy spam (daily) as of late and needed to make a change where new members first five post need to be approved first by a moderator.

What are the PC numbers on the circuit boards in the amp?

From what I have seen of pictures of this amp it looks like the preamp board might be a PC 5066, or 5067, as this is where I think your issue now is.

The power transformer has nothing to do with your issue at this point.

Subject: Re: 1974 Kustom 1-b bass amp

Posted by [Hugh Andrews](#) on Fri, 21 Sep 2018 13:01:12 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hey, totally understand the precaution. The preamp board is PC 5128 REV2. The power board is PC 5131 Rev 0.

Subject: Re: 1974 Kustom 1-b bass amp

Posted by [Hugh Andrews](#) on Fri, 21 Sep 2018 20:37:24 GMT

[View Forum Message](#) <> [Reply to Message](#)

The PC5128 is indeed very similar to the PC 5066/67.

Subject: Re: 1974 Kustom 1-b bass amp
Posted by [Hugh Andrews](#) on Sat, 22 Sep 2018 20:38:28 GMT
[View Forum Message](#) <> [Reply to Message](#)

This was way too easy! It was just a 100 ohm resistor way out of whack on the power board. Ordered an ESR meter to check the caps. Oh well, I'll probably need it on another project.

Subject: Re: 1974 Kustom 1-b bass amp
Posted by [steven](#) on Sun, 23 Sep 2018 10:16:45 GMT
[View Forum Message](#) <> [Reply to Message](#)

Good news to hear!
