
Subject: Kasino concert

Posted by [brokenwheel](#) on Mon, 06 Mar 2023 16:25:14 GMT

[View Forum Message](#) <> [Reply to Message](#)

i cut this off the power switch is this the correct !!! Now i have a loud hum or buzzzzzzzz
i all so changed the power cord to a 3 prog grounding the ground leg to the chase
it appears to be a

.022 -600DC

+ - 10% 225PX Or + - 10% 225Fx ??

this was sodered to the power switch to the chassie

AISo

i do not have the Reverb tank Yet i did locat one and,

wondering how this would be mounted and,

is there any thing i need to know on the wiring the reverb back in ..

i would like to post a picture of what i did but it appears i can not just yet

thank you all

Subject: Re: Kasino concert

Posted by [stevem](#) on Tue, 07 Mar 2023 12:23:49 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hello.

Yes cutting out that .022 uf cap removes the polarity function and the chance of getting shocked,
it will also produce a louder buzz sound when you hands are not touching the strings.

The Concert model was the PA head .

The reverb tank was hung upside down from two Aluminum tubes the spanned the tank and the
amp from front to rear.

These ends of these tubes where crushed flat and drilled out so that 6/32 machine screws held
the bars to the top of the chassis.

If you pm me your email I can send you pictures of what the set up looks like.

I have to approve your post until you have made 5 of them and then they will just go right up to the
board.
