

---

Subject: Re: 250-4

Posted by [kb0rex](#) on Thu, 14 Jul 2022 17:19:09 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

now it looks like noise is being introduced somewhere in the preamps, I have a parasitic oscillation on the wave form on all preamp and 5069 board, gets worse the higher the frequency. So far been a bugger to isolate. any good way to jumper past the 3 boards one at a time to find problem? I can put my scope on the input and when I turn it up just a little boom trash on top of sine wave.Hmmmm

---