
Subject: Re: Kustom 100 blowing fuse
Posted by [steven](#) on Fri, 17 May 2019 17:40:23 GMT
[View Forum Message](#) <> [Reply to Message](#)

Sorry, Q3 on the 5033 board crosses to a nte128 NPN type.

It's original RCA number is 38735.
