

---

Subject: Re: A-4 Repair

Posted by [steven](#) on Sun, 11 Feb 2018 11:24:19 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Yes, that's .60 volts even on the latter 703 and 704 boards.

I would just replace those 3 transistors since it's a pain to get at them and hopefully be done with it!

For voltage test purposes I have long 3 wire extension leads that I solder in that start off in Molex connectors so I do not have to fret about them shorting out to each other.

---