

---

Subject: pot meters

Posted by [Benno](#) on Thu, 27 Jun 2024 21:03:21 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hello all,

I need to replace the 15 kOhm volume pot on a KUSTOM 100-2, but it is very difficult to find. Most of all because of the 5/8" threaded bushing.

Any suggestions?

Thanks,

Ben

---

---

Subject: Re: pot meters

Posted by [stevem](#) on Thu, 27 Jun 2024 22:07:11 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Is the pot physically ok, just very scratchy and intermittent even after flushing it out well with cleaner?

Do you have the pot removed from the board?

---

---

Subject: Re: pot meters

Posted by [Benno](#) on Sun, 30 Jun 2024 12:35:44 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I removed the potmeter and opened it. One slider runs fine between 0 and 15k. The other slider sticks to 15 k till half way. The carbon track is damaged.

Again, where to find a 15k potmeter with a long bushing?

---

---

Subject: Re: pot meters

Posted by [stevem](#) on Sun, 30 Jun 2024 14:26:30 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

They are near impossible to find these days.

Sometimes if you're very careful you can bend the wiper over just enough to ride on untouched resistance trace.

I have a 10K out of a K300 pA I can send you?

---