

---

Subject: Kustom III PA

Posted by [Autoharp](#) on Sun, 19 Apr 2015 04:02:43 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I am working on this amp for Daf, it appears that the biggest issue is very dirty pots - I can handle that - but the output transistors seem to be running very hot. There is no forced cooling and the heat sink looks inadequate. Any thoughts? It seems to work fine otherwise.

---