

---

Subject: repairing k150-8 plexi

Posted by [natedriver](#) on Sat, 28 Nov 2015 15:13:44 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I have a k150-8 plexi head that is blowing fuses. I built a bulb limiter. I am getting 55v and -55v off the filter caps. the schematic for board 5032 shows 39.5v and -39.5v.

Am I missing something here? Any help would be appreciated before I move forward with trouble shooting the power amp board thanks. Nate

---