
Subject: Re: A-4 Repair

Posted by [chicagobill](#) on Sat, 25 Aug 2018 04:15:51 GMT

[View Forum Message](#) <> [Reply to Message](#)

The 15 volts is a typo. If it wasn't there would be about 13 volts across the bias diode string.
The usual voltage would be about -0.5 volts.

Does the distortion occur with both preamp channels?
