

---

Subject: reverb issue

Posted by [cassent5150](#) on Tue, 23 Mar 2010 12:41:30 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Re: Reverb issue again!! [message #13233 is a reply to message #13162 ] Tue, 23 March 2010 08:37

cassent5150

Messages: 49

Registered: August 2009 Member

OK I give up on the reverb board until I can get the tools to check the components. Its like I seen in other postings, the components in the board are not shorted but may still be bad. I can change out transistors all day long but I have no way to tell if the new transistors I'm replacing them with are good. Its like shooting in the dark. So I jerked the reverb board out of a k100-5 I wasn't using and we're back up and running with the K200-5 and it sounds great.

I'm going to put the bad reverb board in the K100 and still try and figure out what the heck is going on with it. The values at Q801 are off at the collector, does anyone know what components might effect that value or things I may do to pinpoint the problem??????

-----  
Steve C

---