

---

Subject: Re: Kustom 100 blowing fuse  
Posted by [timetraveler](#) on Wed, 24 Apr 2019 12:33:46 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

that might be the problem i replaced Q5 with a nte128 when it should be a nte 129

---