

---

Subject: Re: A-4 Repair

Posted by [Jonomega3](#) on Wed, 31 Jan 2018 17:47:47 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

OK, I removed the 4 coupled resistors and cap at R705 and at C702 there was a 22uf 25v cap coupled with a 1kv cap. If you look at C702 it says "10" as the value would that be the same as 1kv? Which is a very small cap, it looks original but I wasn't sure of that value.

Also if you look at pic 5 of the pics I sent there is a large ceramic .02 cap there that I cant seem to locate on the schematic, its actually hooked to ground and according to the schematics there is no .02 caps anywhere, remove that you think?

---