

---

Subject: Re: A-4 Repair

Posted by [Jonomega3](#) on Fri, 24 Aug 2018 22:22:57 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

found RCA NOS 40409-10 on Ebay and put them in...good news the amp actually works now, bad news the distortion and low volume still there. Checked some voltages and getting voltages everywhere but at the connection at the 40410 base where schematics say should be 15 volts, getting about 1 volt at the 1st diode

---