
Subject: Re: Dead K 100 Piggyback

Posted by [Breakersbass](#) on Wed, 12 Oct 2016 16:33:51 GMT

[View Forum Message](#) <> [Reply to Message](#)

Thanks Steve Sorry but had Hurricane issues all week.I meant the transistor that was in the amp was a C644 which could be a Japanese 2sc 644 but I cant be positive.I changed it out with an NTE.Also When I added 20 ohms the the wire wound resistor tied to the pilot lamp It works.The original ohms out correctly.Someone also put a Capacitor tied to the Positive feed on the bulb.AnywayI got her up and running
Thanks Alan
