

---

Subject: Re: A-4 Repair

Posted by [steven](#) on Mon, 12 Feb 2018 12:29:04 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I would also lift one end of cr704 and cr705 to test them for shorts or leakage.

---