

---

Subject: Re: K150-6 pumps out DC voltage when powered on.  
Posted by [corybrown](#) on Mon, 09 Mar 2020 01:56:04 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Went ahead and pulled Q6 from the board. It tested fine. I didn't try swapping with the nte129 that I have because it doesn't have the heat sink.

Thanks

---