

---

Subject: Re: Repair advise

Posted by [Jonomega3](#) on Sun, 11 Aug 2013 20:17:34 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I'm so sorry chicagobill, Its a case of "old geezeritis"! I took a better look with a BIGGER magnifying glass and you're totally right its a burn mark. It sucks getting old, as the eyes get worse I become more certain of what im not seeing, haha.

Anyway, I put alligator clips connecting the straight board to the chassis and it was cleaner sounding. I did love the sound of the amp but you're right it had a little more noise than it probably should've. So, it probably wouldn't hurt to fix up the mess made in the power section if possible.

---