

---

Subject: Re: Schematic Accuracy

Posted by [bluezebra](#) on Mon, 17 Feb 2014 16:33:34 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The tremolo schematic seems to be following my board very close. The only questionable component seems to be R152 which according to the revision was penciled in as a 15k from a 10k. My board has a 47k (which appears to be original). I don't know whether to stay original or follow schematic.

---