

---

Subject: Re: reverb issue

Posted by [cassent5150](#) on Sat, 27 Mar 2010 00:20:17 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I got these from Mouser Electronic Supply. They have a broken white line down one side. OK, the transistors that can be pin in all directions is going to be a problem. I don't get it. So if they're not marked and there is no standard for pin position you have to find the data sheet to get it? Guess I better get the data sheets on the transistors I have on hand.

---