

---

Subject: Re: Schematic Accuracy

Posted by [bluezebra](#) on Mon, 17 Feb 2014 16:07:06 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Stevem

I got the reverb issue fixed. It now turns off and on...but now the tremolo no longer works...I guess it fixes the thumping problem...lol

Also, another schematic thing...I don't have a Q117 Q118 in the position shown on the Rev 3 or Rev 4 schematic. I do have a transistor about to fall off the corner of the board where the grey effects wire comes into the board. That's not shown on the diagram either. That's part of reverb circuit so I'm good on that one.

After changing a few value resistors and checking all of the transistors my +8 is now at +10 and -10.4. That's closer than what it was. Coming out of the transformer I read +41 and -39.9. I don't know if it is supposed to be perfectly equal or I have a transformer problem. The amp sounds great.

---