

---

Subject: Re: Kustom 100 blowing fuse

Posted by [timetraveler](#) on Fri, 17 May 2019 16:51:13 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

rca 38135 is what is in it now on the 5033 circuit board. rechecked the transistors and diodes one diode CR-2 was facing the wrong direction. reconnected everything and tested still some problem (fuse blows and Q8 output transistor gets blown)

---