

---

Subject: Re: Schematic Accuracy

Posted by [bluezebra](#) on Mon, 10 Feb 2014 22:10:43 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thanks Bill

gives me some idea of where to look. I do note that when the intensity pot is turned all the way up the thumping seems to be muffled somewhat.

It didn't do this before I changed the tantalums to electrolytics and changed most of the carbon comps to get rid of the an intermittent crackle, that is now gone! Fix one problem and get another...!

---