

---

Subject: Re: Repair

Posted by [steven](#) on Fri, 30 Sep 2022 15:27:39 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I would first suggest that you peel back the foam covering the top of the tank and see if both springs in there are still connected on each end to the transducer.

---