

---

Subject: Kustom K150 Death Cap? Getting voltage through guitar cord.

Posted by [ARKustom](#) on Thu, 05 Oct 2017 15:48:33 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I recently picked up a 1972 K150 head and 212B cabinet. This morning I leaned against the instrument lead shirtless and got a little sting from it. I noticed last night that it also buzzes quite a bit if my hand is not in contact with a conductive part of my bass. Does this thing have a death cap? How should I go about removing it? I have decent knowledge of working on an amp and decent soldering skills.

---