

---

Subject: K250 bass amp issues

Posted by [Jelloman774](#) on Sat, 17 Apr 2010 15:40:47 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Of the two capacitors that are in the amp I had the one on the left replaced a handfull of years ago. Now its making the same sound it made when the one went. The one I had replaced has CG452U50D1: 4,500uF 50V Aluminum Electrolytic Capacitor (Screw Terminals) as a part number.

Is it the same part number for both capacitors or is it two different ones? Any help would allow me to sleep at night.

---

---

Subject: Re: K250 bass amp issues

Posted by [chicagobill](#) on Sat, 17 Apr 2010 18:30:04 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Yes, the two large caps are the same part number.

Sleep well.

---

---

Subject: Re: K250 bass amp issues

Posted by [Jelloman774](#) on Sat, 17 Apr 2010 18:33:50 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thank you so much!

---