

---

Subject: Re: Repair

Posted by [NLKustom](#) on Thu, 07 Apr 2022 20:25:07 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thanks for the help Steve.

So I checked the tank again, the RCA chord going to the "input" jack is not showing 0 on the ohm meter on the shield connectors.

The RCA chord going to the "output" jack is showing 0 on the ohm meter, so I'm assuming it's shielded.

The reverb tank has the "input" jack farthest away from the power transformers, looking at it from the front of the amp., and the "output" jack is closest to the transformers, or in the middle of the amp.

The tank is an Accutronics, these are the numbers stamped on it. 031-005-00. 25-75-301.

23572-0. 4FB2A1A. It looks like someone has peeled back the foam on both ends of the tank for some reason, to look inside I suppose. Everything looks fine in there, the foam is still in place.

When I shake the amp I can hear the reverb springs through the speakers.

---