

---

Subject: Re: 250-4

Posted by [kb0rex](#) on Fri, 24 Jun 2022 21:22:09 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Maybe we are finding something I have +5 volts or so at the collector of q6 on the cathode side of cr 4, so somethings not right around the q6 area. When I got this mess this transistor was blown in half. I replaced it makes me wonder now if it got blown again.

---