

---

Subject: Re: Repair

Posted by [steven](#) on Sat, 08 Oct 2022 16:05:02 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Sounds like a bad solder connection to me and it may be at the rca jack on the circuit board where the output of the tank plugs in.

---