
Subject: Re: Kustom 100 blowing fuse
Posted by [timetraveler](#) on Sun, 19 May 2019 12:48:51 GMT
[View Forum Message](#) <> [Reply to Message](#)

the .5 ohm 5 watt resistors are reading .7 ohms which is outside of the 10% tolerance range would that cause the fuse to blow?
