

---

Subject: Re: 250-4

Posted by [kb0rex](#) on Fri, 24 Jun 2022 15:00:59 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Remeasuring this morning I have +.210 on speaker output and 36.46 on +- rails. With all preamps turned down. Could the diff amps have been stressed when this got cooked? I just can't remember how they work but I seem to recall they must be the phaser in this amp. I can't figure out what q3 does. Almost want to put a pot in for the bias to play with it.

---