

---

Subject: Re: Kustom 100 blowing fuse

Posted by [timetraveler](#) on Thu, 06 Jun 2019 00:27:12 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I may have the capacitors instaled in the wrong direction

using this diagram is confusing as to which direction the positive side goes. on the lower diagram it has a plus sign on some of the caps but they are configured differently in the upper diagram.

file:///C:/Users/anoth/Downloads/Kustom%20PC5033%20Power%20Amp%20(Rev.6)%20Schematic%20(1).pdf

---