

---

Subject: Re: A-4 Repair

Posted by [chicagobill](#) on Sun, 11 Feb 2018 04:54:24 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I think that you may have reversed the Collector and Emitter readings of Q703.

The rest of the voltages are pretty much what they should be. The 60 on the emitters is a typo, I think it should be 0.6 volts.

Is the current problem now a fuzzy distortion that is constantly there in the background and not just a distortion on peak signals?

And for now I would remove the cap and resistor from the output jack.

---